

2023 Update

Lotus Lake

Located in eastern Chanhassen, Lotus Lake is one of three headwaters of Purgatory Creek. Water flows out of Lotus into the south fork of Purgatory Creek, which eventually meets up with the two other forks of the creek.

From June to September every year, District staff visit the lake every two weeks to collect water samples and take readings. Samples are sent to a laboratory to be tested for nutrients and other compounds. Staff also measure water clarity by lowering a Secchi disk into the water and measuring how deep it goes before it is no longer visible. The data indicates the lake's health based on standards set by the Minnesota Pollution Control Agency (MPCA).

Lotus Lake is classified as a "Deep Lake" by the MPCA. To be considered healthy, the lake must have very low average phosphorus and chlorophyll-a levels and average water clarity of 1.4 meters (4.6 feet) or greater. See summary below. Additional details are located on the next page.



Total Phosphorus: Since the alum treatment in 2018, the lake has consistently met the MPCA standard (<0.04 mg/L) In 2023, the average level was 0.031 mg/L.



Chlorophyll-a: The lake has never met the MPCA standard (<14 µg/L). In 2023, the average chlorophyll-a reading was 24.6 µg/L.



Water clarity: Since 2013, the lake has consistently met the MPCA standard (>1.4 meters) for water clarity except for one year. The average reading in 2023 was 2.0 meters.



Plants: Eurasian Watermilfoil and Curly-leaf Pondweed were targeted with a single Diquat herbicide treatment (22.92 acres) in the spring of 2023.

Lake & watershed characteristics

Lake size	248 acres
Average lake depth	16 feet
Maximum lake depth	31 feet
MPCA lake classification	Deep lake
Watershed size	1,408 acres
Impervious surface	16% of watershed
Impaired Waters listing	Mercury, nutrients, fish
Common fish	Bluegill, Yellow Bullhead, Walleye, Black Crappie
Invasive species	Eurasian Watermilfoil, Common Carp, Curly-leaf Pondweed, Brittle Naiad




Watershed Boundary



LAKE SPECIES -25-**Native Aquatic** 22 Ann **Plant Diversity** Duck 17 Lucv 15 -20-How does Lotus Lake Red Rock 14 compare to other lakes Silver 14 12 in the District in **number** Staring 12 Mitchell of native plant species? 12 10 Round

RPBCWD Office, 18681 Lake Drive East, Chanhassen, MN 55317 rpbcwd.org info@rpbcwd.org



@rpbcwd

Lotus Lake Water Quality by the Numbers

For the last few years, **Lotus Lake** has consistently met the clean water standards set by the MPCA, except for Chlorophyll-a. The graphs below show water quality trends over time with the red line representing the MPCA standard for **deep lakes**.

Water Quality Report Card

rpbcwd.org/grades

